

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA Division Director

GREGORY S. BELL Lieutenant Governor

Minerals Inspection Report

Reviewed

PRAS

		Report Date: 07/14/201	4		
Mine Name: Bromide Basin		Permit Number:	S/017/0031	Mine Status:	Active
Ope	rator Name: Bromide Mining LLC.	Inspection Date:	07/09/2014	Permit Fees:	Paid
Inspector(s): Wayne Western		Inspection Time:	9:30 - 10:30 am	Bond Amount:	\$57,600
Attendee(s): John Reay		Weather:	warm and sunny	Bond Escalation:	07/22/2017
Insp	ection Purpose: Routine inspection			Prior Inspection:	05/21/2014
Pern	bond is current nittee must get an agreement with the BLM and nittee must divert water so that it flows in the nat			work.	
	Elements of Inspection			raluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds				
2.	The bond is adequate. As of date of inspection, the Operator had not Public Safety (shafts, adits, trash, signs, highw		rfield County on a r	oad maintenance agreer	ment.
3.	Protection of Drainages/Erosion Control				
3.	The Operator needs to direct water coming out ditch.	of the adit into a culvert befor	e it crosses the road		er flow into a
4.	Deleterious Material				
5.	Roads (maintenance, surfacing, dust control, sa	afety)			
	The Operator needs to constantly keep the road overnight. Water should be diverted into culve		The Division unde	erstands that new spring	s can appear
6.	Reclamation				
7.	Backfilling/Grading (trenches, pits, roads, high	nwalls, shafts)			
8.	Soils				
9.	Revegetation				
10.	Other				

Inspector's Signature:

CC

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M017-Garfield/S0170031-Bromidebasin/inspections/Insp07062014A.pdf



Mine: S/017/0031 Inspected: 07/09/2014



Water flowing out of the adit. Looking inward.



Water flowing out of the adit and then across a road before going into a ditch.



Ditch where water eventually flows into.



Pond where water eventually flows into.

